

Final Reclamation Inspection

November 13, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 322602

Inspection Document #: 718801063

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Arens #G12-25D Tank
Location ID: 322602



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards as weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*) were observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: Arens #G12-25D Tank
Location ID: 322602



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: Arens #G12-25D Tank
Location ID: 322602



Photo 5. Photo taken of the tank battery location, facing south. Photo illustrates that final reclamation activities have not taken place at the tank battery and bare ground, gravel, and weedy annual vegetation were observed across the location.



Photo 6. Photo taken of the tank battery location, facing east. See comments under Photo 5.

Inspection Photos

Location Name: Arens #G12-25D Tank

Location ID: 322602



Photo 7. Photo taken of the tank battery location, facing southeast. See comments under Photo 5.



Photo 8. Photo taken of the access road to the location, facing west. Photo illustrates that final reclamation activities have not taken place along the road.



Inspection Photos
Location Name: Arens #G12-25D Tank
Location ID: 322602



Photo 9. Photo taken of the reference area to the location, northeast of the location, facing northeast. Photo illustrates perennial grass vegetation and kochia.