

# Final Reclamation Inspection

November 13, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 322727

Inspection Document #: 718801076

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LATHAM #2-1  
Location ID: 322727



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards and gravel was observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: LATHAM #2-1  
Location ID: 322727



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: LATHAM #2-1  
Location ID: 322727



**Photo 5.** Photo taken of the access road to the location, facing northwest. Photo illustrates that final reclamation activities have taken place, but gravel remains across the access road and vegetation has not established to Rule 1004 standards.



**Photo 6.** Photo taken of ground cover at the location. Photo illustrates perennial grass and gravel.

Inspection Photos  
Location Name: LATHAM #2-1  
Location ID: 322727



**Photo 7.** Photo taken of the tank battery location, facing northwest. Photo illustrates that a portion of the location remains as an access road for another location and midstream equipment remains at the location.



**Photo 8.** Photo taken of the tank battery location, facing southwest. See comments under Photo 7.

Inspection Photos  
Location Name: LATHAM #2-1  
Location ID: 322727



**Photo 9.** Photo taken of the southern portion of the tank battery location, facing southwest. Photo illustrates that final reclamation activities have taken place at this portion of the location, but vegetation has not established to Rule 1004 standards and weedy annual vegetation including cheatgrass (*Bromus tectorum*) was observed.



**Photo 10.** Photo taken of the tank battery location, facing west. See comments under Photo 9.

Inspection Photos  
Location Name: LATHAM #2-1  
Location ID: 322727



**Photo 11.** Photo taken of the reference area to the location, north of the location, facing northwest. Photo illustrates perennial grass.

