

Final Reclamation Inspection

November 13, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 322727

Inspection Document #: 718801078

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Seether PC #G01-33D

Location ID: 322727



Photo 1. Photo taken of the abandoned well location, facing north. Photo illustrates that there is no evidence of oil and gas disturbance from the abandoned well location and based on records the well was never drilled. Another well was drilled at the site (Well API# 123-11952) and has been inspected separately.



Photo 2. Photo taken of the abandoned well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: Seether PC #G01-33D
Location ID: 322727



Photo 3. Photo taken of the abandoned well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the abandoned well location, facing west. See comments under Photo 1.

