

Final Reclamation Inspection

November 13, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 319591

Inspection Document #: 718801083

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ARD #11-6
Location ID: 319591



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, and vegetation establishment at the well location appears to meet reference area conditions.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: ARD #11-6
Location ID: 319591



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: ARD #11-6
Location ID: 319591



Photo 5. Photo taken of the access road to the well location, facing east. Photo illustrates that vegetation establishment appears to meet Rule 1004 standards.



Photo 6. Photo taken of the tank battery location, facing east. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards.

Inspection Photos
Location Name: ARD #11-6
Location ID: 319591



Photo 7. Photo taken of the tank battery location, facing northwest. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing west. See comments under Photo 6.

Inspection Photos
Location Name: ARD #11-6
Location ID: 319591



Photo 9. Photo taken of the reference area to the location, south of the tank battery location, facing south. Photo illustrates perennial grass vegetation.