

Final Reclamation Inspection

November 21, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 317689

Inspection Document #: 718801104

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE #4
Location ID: 317689



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards as weedy annual vegetation was observed across the location, including cheatgrass (*Bromus tectorum*).



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: STATE #4
Location ID: 317689



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: STATE #4
Location ID: 317689



Photo 5. Photo taken of the access road to the location, facing south. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed along the road.



Photo 6. Photo taken of the reference area to the location, east of the location, facing southeast. Photo illustrates perennial grass and weedy annual vegetation.