

Inspection Photos

September 12th, 2025

Operator: Noble Energy Inc.

Location ID: 330218

Inspection Document #: 714002609

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Rubix A 32-04
Location ID: 330218



Photo 1. Aerial imagery of the Well Pad (highlighted in Red). Access Road (highlighted in yellow) and Tank Battery (highlighted in Blue). Note: Tank battery is associated with its own location ID #420814.

Inspection Photos
Location Name: Rubix A 32-04
Location ID: 330218

September 12, 2025
221° SW



Photo 2. Ground view of the well pad taken from the northern edge facing center.



Photo 3. Cardinal view taken from the center of the disturbance facing north.



Photo 4. Cardinal view taken from the center of the disturbance facing south.

Inspection Photos
Location Name: Rubix A 32-04
Location ID: 330218

September 12, 2025
305° NW



Photo 5. Reference area.