

# Inspection Photos

September 12th, 2025

Operator: Noble Energy Inc.

Location ID: 306566

Inspection Document #: 714002603

County: Weld

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Shoemaker A 12-1  
Location ID: 306566



**Photo 1.** Aerial imagery of the Well Pad (highlighted in Red) and Tank Battery (Highlighted in Blue). Note: Tank battery is associated with its own location ID #485935.

Inspection Photos

Location Name: Shoemaker A 12-1

Location ID: 306566

September 12, 2025  
304° NW



**Photo 2.** View of well pad agriculture field which was recently planted, vegetation is in a state of early germination.

