

Inspection Photos

September 12th, 2025

Operator: Noble Energy Inc.

Location ID: 305963

Inspection Document #: 714002610

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Novacek C 28-7
Location ID: 305963




Photo 1. Aerial imagery of the Well Pad (highlighted in Red) and Access Road (highlighted in yellow). Note: Tank battery (Not pictured to the North) is associated with its own location ID #481156.



Photo 2. View of the well pad agriculture field which has been harvested.