

**Inspection Photos**  
**Location Name: Williams 2-18**  
**API Number: 125-07981**



**1. Lease sign missing from frame at well location.**




**2. View of wellhead.**

Inspection Photos  
Location Name: Williams 2-18  
API Number: 125-07981



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos  
Location Name: Williams 2-18  
API Number: 125-07981



5. Damage to Meter Shed roof.



6. Gas Meter inside Meter Shed.