

Inspection Photos

12/04/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 417777

Inspection Doc: 719200529

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417777



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417777



Photo 2: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417777



Photo 3: Photos showing an example of wellhead signage at the location with incorrect or unclear Operator information; comply with Rule 605.d.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417777



Photo 4: Photos showing a wellhead at the location with insufficient wildlife egress; the bunny board has fallen into the well cellar. Comply with Rule 902.b. and maintain wildlife protection BMPs.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417777



Photo 5: Photos showing an example of the western and southern interim areas, respectively. Interim areas are progressing towards 1003 requirements; weed control will likely be required in 2026.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources