

Inspection Photos

API: 009-06593

Operator: ENERGY ALLIANCE COMPANY INC

Inspection Date: 12/8/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. 2024 aerial shows the access road at red arrow remains visible. The yellow arrow points to the Meter run 1370' NW of wellhead.

