

Inspection Photos

API: 009-06134

Operator: SAMSON OIL COMPANY

Inspection Date: 12/8/2025

County: BACA



Inspection Photos



Photo 1. Drone aerial photo facing southwest. Red arrows points to the gathering risers and the former wellsite location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06134 | Date: 12/8/2025

Inspection Photos



Photo 2. Drone aerial photo facing southwest toward the former wellsite location. The location is fenced but desirable vegetation has not established. The dark vegetation inside the fence is mostly undesirable weeds (Kochia?)



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 3. Drone aerial photo facing east at the former wellsite. The area is bare of vegetation and appears to be impacted from an historical spill from wellsite operations.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06134 | Date: 12/8/2025

Inspection Photos



Photo 4. Drone aerial photo facing northeast at the former wellsite. Red arrow points to abandoned pipe risers that remain at the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06134 | Date: 12/8/2025