

Howard USX A09-10

Date of Incident: 3/18/24
API#/Facility#: 05-123-24495
Legal Description: NWSE Sec: 9 Twp: 6N R: 64W M: 6
Latitude/Longitude: 40.498780, -104.552830
Remediation #: 32221
Fremont No: C024-057

Legend

- Soil Sample Location
- Impacted Sample Location

BKG04 ○ FL02 2Ft

● FL03 2Ft

○ FL04 2Ft

BKG05

○ FL05 2Ft

○ FL06 2Ft

○ FL07 2Ft

○ FL01 2Ft

