

# Inspection Photos

12/04/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 420223

**Inspection Doc:** 719200535

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 420223



**Photo 1:** Photos showing an overview of the location looking northeast and southwest, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 420223



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 420223



**Photo 3:** Photos showing erosion, rilling and sediment deposition occurring on cut slopes behind production equipment. Comply with 1002.f. and implement or maintain stormwater BMP's.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 420223



**Photo 4:** Photos showing the western and southern interim areas, respectively. Interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources