

Inspection Photos
Location Name: Lueking 11-19 5N46W
API Number: 125-09327



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Lueking 11-19 5N46W
API Number: 125-09327




3. View of open-ended flowline and riser at wellhead location.



4. Well location overview.

Inspection Photos
Location Name: Lueking 11-19 5N46W
API Number: 125-09327



5. Lease sign at gathering location.

6. Gas meter inside meter shed.

Inspection Photos
Location Name: Lueking 11-19 5N46W
API Number: 125-09327



7. View of black poly line stubbed up at remote gathering location.



8. Gathering location overview.