

Inspection Photos
Location: Muffins 14-18
Location ID: 308878
API # 05-071-08759



Photo 1 – Well Placard

Photo 2 – Wellhead and equipment

Inspection Photos
Location: Muffins 14-18
Location ID: 308878
API # 05-071-08759




Photo 3 – Impacted soils



Photo 4 – Impacted soils

Inspection Photos
Location: Muffins 14-18
Location ID: 308878
API # 05-071-08759



Photo 5 Pit Facility ID 301105

Photo 6 – Pit Flowline