

Inspection Photos
Location Name: O. Lueking 10-19
API Number: 125-06978



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: O. Lueking 10-19
API Number: 125-06978



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: O. Lueking 10-19
API Number: 125-06978



5. Gas Meter inside Meter Shed.



6. Flowline riser with bolted cap at gathering location.