

Final Reclamation Inspection

November 25, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 330038

Inspection Document #: 718801127

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-B/R #15-20
Location ID: 330038



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and gravel and weedy annual vegetation were observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: HSR-B/R #15-20
Location ID: 330038



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: HSR-B/R #15-20
Location ID: 330038



Photo 5. Photo taken of the access road to the location, facing west. Photo illustrates that final reclamation activities have taken place, but the road does not meet Rule 1004 standards as gravel and weedy annual vegetation were observed across the location.



Photo 6. Photo taken of ground cover at the location. Photo illustrates kochia (*Bassia scoparia*) and gravel.



Inspection Photos
Location Name: HSR-B/R #15-20
Location ID: 330038



Photo 7. Photo taken of the reference area to the location, north of the location, facing northwest. Photo illustrates perennial grass and kochia (*Bassia scoparia*).