

Final Reclamation Inspection

November 25, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 330036

Inspection Document #: 718801133

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-B/R "D" #10-20
Location ID: 330036



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: HSR-B/R "D" #10-20
Location ID: 330036



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: HSR-B/R "D" #10-20
Location ID: 330036



Photo 5. Photo taken of the access road to the location, facing east. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards as weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 6. Photo taken of ground cover at the location. Photo illustrates kochia (*Bassia scoparia*).



Inspection Photos
Location Name: HSR-B/R "D" #10-20
Location ID: 330036



Photo 7. Photo taken of the reference area to the location, east of the location, facing north. Photo illustrates perennial grass vegetation.