

Final Reclamation Inspection

November 25, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329980

Inspection Document #: 718801135

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-B/R "D" #9-20
Location ID: 329980



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: HSR-B/R "D" #9-20
Location ID: 329980



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: HSR-B/R "D" #9-20
Location ID: 329980



Photo 5. Photo taken of the access road to the location, facing east. Photo illustrates that final reclamation activities do not appear to have taken place, and bare ground and weedy annual vegetation including kochia (*Bassia scoparia*) were observed.



Photo 6. Photo taken of the access road to the location, facing southwest. See comments under Photo 5.

Inspection Photos
Location Name: HSR-B/R "D" #9-20
Location ID: 329980



Photo 7. Photo taken of the reference area to the location, north of the location, facing north. Photo illustrates perennial grass vegetation and kochia (*Bassia scoparia*).

