

# Final Reclamation Inspection

November 25, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329981

Inspection Document #: 718801137

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-B/R #16-20  
Location ID: 329981



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-B/R #16-20  
Location ID: 329981



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-B/R #16-20  
Location ID: 329981



**Photo 5.** Photo taken of the access road to the location, facing west. Photo illustrates that final reclamation activities appear to have taken place, but the road does not meet Rule 1004 standards as bare ground and weedy annual vegetation including kochia (*Bassia scoparia*) were observed.



**Photo 6.** Photo taken of the access road to the location, facing east. See comments under Photo 5.



Inspection Photos  
Location Name: HSR-B/R #16-20  
Location ID: 329981



**Photo 7.** Photo taken of the reference area to the location, east of the location, facing north. Photo illustrates perennial grass vegetation and kochia (*Bassia scoparia*).

