

Final Reclamation Inspection

November 25, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 322829

Inspection Document #: 718801143

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UCLI #6-1
Location ID: 322829



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: UCLI #6-1
Location ID: 322829



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: UCLI #6-1
Location ID: 322829



Photo 5. Photo taken of ground cover at the location. Photo illustrates kochia (*Bassia scoparia*).



Photo 6. Photo taken of the reference area to the location, north of the location, facing northwest. Photo illustrates perennial grass vegetation and kochia (*Bassia scoparia*).