

# Final Reclamation Inspection

November 25, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 323339

Inspection Document #: 718801146

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: UCLI #6-3  
Location ID: 323339



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: UCLI #6-3  
Location ID: 323339



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: UCLI #6-3  
Location ID: 323339



**Photo 5.** Photo taken of the access road to the location, facing south. Photo illustrates that a gate remains along the reclaimed access road.



**Photo 6.** Photo taken of the access road to the location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards along the access road and weedy annual vegetation including kochia (*Bassia scoparia*) was observed.



Inspection Photos  
Location Name: UCLI #6-3  
Location ID: 323339



**Photo 7.** Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates perennial grass vegetation.