

Inspection Photos
Location Name: Lueking 4-19
API Number: 125-06309



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Lueking 4-19
API Number: 125-06309



3. Dried vegetation and production related debris inside well fencing.



4. Gas Meter inside Meter Shed.

Inspection Photos
Location Name: Lueking 4-19
API Number: 125-06309



5. Well location overview.



6. Well location overview.