

Final Reclamation Inspection

December 9, 2025

Operator: 8 NORTH LLC - 10575

Location ID: 415459

Inspection Document #: 7203000014

Weld County, CO

Isaac Thibedeau & Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DF RANCH #1161-17-12
Location ID: 415459



Photo 1. Photo taken from the beginning of access road, facing north. Photo illustrates the locations acces road is vegetated with desirables species. Fencing still present and needs to be removed.



Photo 2. Photo taken from the beginning of access road. Good Reclamation practices represented but needs to be removed.

Inspection Photos
Location Name: DF RANCH #1161-17-12
Location ID: 415459



Photo 3. Photo taken from the location, facing west. This photo illustrates vegetation growth of native species. Fence in the distance has collected tumble weeds and needs to be removed.



Photo 4. Photo taken from the location, facing north. See comments under Photo 3.

Inspection Photos
Location Name: DF RANCH #1161-17-12
Location ID: 415459



Photo 5. Photo taken from location facing east. See comments under Photo 3.



Photo 6. Photo Taken from the location facing south. See comments under Photo 3.