

Inspection Photos
Location Name: Camenish 1
Location ID: 333225



Photo 1 Location entrance.



Photo 2 Tank battery overrun with dead vegetation.

Inspection Photos
Location Name: Camenish 1
Location ID: 333225



Photo 3 Tank battery overrun with dead vegetation.

Photo 4 Gas meter overrun with dead vegetation.

Inspection Photos
Location Name: Camenish 1
Location ID: 333225



Photo 5 Vertical separator & ECD are overrun with dead vegetation.

Photo 6 Well site overrun with tall dead vegetation.

Inspection Photos
Location Name: Camenish 1
Location ID: 333225



Photo 7 Well site signs are in the dead vegetation.

Photo 8 Ancillary equipment in the tall dead vegetation.

Inspection Photos
Location Name: Camenish 1
Location ID: 333225



Photo 9 Pumpjack in the dead vegetation.

Photo 10 Wellhead in the tall dead vegetation.