

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 1 Location.

Photo 2 ECD, Horizontal Heated Separator.

Inspection Photos
Location Name: Hein 2
Location ID: 332959




Photo 3 Gas Meter Runs No calibration records.

Photo 4 Separators.

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 5 Manifold.

Photo 6 Unmarked flow line.

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 7 Tank battery.

Photo 8 Tank battery sign.

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 9 Wellsite.

Photo 10 Wellsite sign.

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 11 Wellhead.




Photo 12 Pumpjack.