

Inspection Photos
Location Name: Alex H Miller 1
Location ID: 318376



Photo 1 Access road over overrun with tall dead vegetation.



Photo 2 Tall dead vegetation around the ancillary equipment.

Inspection Photos
Location Name: Alex H Miller 1
Location ID: 318376



Photo 3 Wellsite.



Photo 4 Tall dead vegetation around the wellhead .

Inspection Photos
Location Name: Alex H Miller 1
Location ID: 318376



Photo 5 Wellsite sign.

Photo 4 Tall dead vegetation around the pumpjack.