

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4517 Entrance to location



Photo # 4520 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4526 Location



Photo # 4532 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4534 Location



Photo # 4543 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4544 Location



Photo # 4565 NW corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4566 SW corner of location



Photo # 4567 South of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4568 SE corner of location



Photo # 4569 NE corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4525 Unused flowlines lack lockout tagout (OOSLAT)



Photo # 4558 Unused flowlines lack lockout tagout (OOSLAT)

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4560 Loose barbed wire fencing on location/wildlife hazard & fencing is in disrepair



Photo # 4561 Loose barbed wire fencing on location/wildlife hazard

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4562 Loose barbed wire fencing on location/wildlife hazard



Photo # 4563 Loose barbed wire fencing on location/wildlife hazard & fencing is in disrepair

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC FEDERAL #2S-95-16-33DP PAD

Location ID: 316603

Date: 11/24/2025



Photo # 4546 Labeling on production tank is in disrepair & lacks required information

