

Final Reclamation Inspection

August 29th, 2025

Operator: PDC Energy

Location ID: 328106

Inspection Document #: 714002849

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Hicks & Johnson Drake FM 1

Location ID: 328106




Photo 1. NAIP aerial imagery (2011) illustrating the well location (red circle), associated tank battery location (blue polygon), and well access road. The tank battery is associated with its own location ID # 464902.



Inspection Photos

Location Name: Hicks & Johnson Drake FM 1

Location ID: 328106



Photo 2. Orthomosaic (drone) imagery taken 8/29/2025 and NAIP aerial imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).



Inspection Photos

Location Name: Hicks & Johnson Drake FM 1

Location ID: 328106



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well).



Inspection Photos

Location Name: Hicks & Johnson Drake FM 1

Location ID: 328106



Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well, access road, presumed flowline, and TB). Crop vegetation at the well pad and access road appear consistent with adjacent reference areas.



Inspection Photos

Location Name: Hicks & Johnson Drake FM 1

Location ID: 328106



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well).



Inspection Photos

Location Name: Hicks & Johnson Drake FM 1

Location ID: 328106



Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well).

