

# Final Reclamation Inspection

August 29th, 2025

Operator: PDC Energy

Location ID: 305138

Inspection Document #: 714002847

Weld County, CO

Corey Mcdonough  
Reclamation Specialist, ECMC



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Hicks P7-23

Location ID: 305138




**Photo 1.** NAIP aerial imagery (2005) illustrating the well location (red circle), associated tank battery location (blue polygon), and well access road. The tank battery is associate with its own location ID #464902.



Inspection Photos

Location Name: Hicks P7-23

Location ID: 305138



**Photo 2.** Orthomosaic (drone) imagery taken 8/29/2025 and NAIP aerial imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).



Inspection Photos

Location Name: Hicks P7-23

Location ID: 305138



**Photo 3.** Drone aerial imagery taken south of well location, facing north (displaying the well).



Inspection Photos

Location Name: Hicks P7-23

Location ID: 305138



**Photo 4.** Drone aerial imagery taken west of well location, facing east (displaying the well, access road, presumed flowline, and TB). Crop vegetation at the well pad and access road appear consistent with adjacent reference areas.



Inspection Photos

Location Name: Hicks P7-23

Location ID: 305138



**Photo 5.** Drone aerial imagery taken north of well location, facing south (displaying the well).



Inspection Photos

Location Name: Hicks P7-23

Location ID: 305138



**Photo 6.** Drone aerial imagery taken east of well location, facing west (displaying the well).



Inspection Photos

Location Name: Hicks P7-23

Location ID: 305138



**Photo 7.** Drone aerial imagery above well location facing downward (displaying the well).

