

# Final Reclamation Inspection

August 29th, 2025

Operator: PDC Energy

Location ID: 464902

Inspection Document #: 714002848

Weld County, CO

Corey Mcdonough  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Hicks Tank Battery

Location ID: 464902



**Photo 1.** 2017 aerial imagery of the tank battery location (highlighted in blue).

Inspection Photos

Location Name: Hicks Tank Battery

Location ID: 464902



**Photo 2.** Drone aerial imagery taken west of TB location, facing east (displaying the TB).



Inspection Photos

Location Name: Hicks Tank Battery

Location ID: 464902



**Photo 3.** Drone aerial imagery taken north of TB location, facing south (displaying the TB). Crop vegetation at the tank battery appear consistent with adjacent reference areas.



Inspection Photos

Location Name: Hicks Tank Battery

Location ID: 464902




**Photo 4.** Drone aerial imagery taken east of TB location, facing west (displaying the TB).



Inspection Photos

Location Name: Hicks Tank Battery

Location ID: 464902



**Photo 5.** Orthomosaic (drone) imagery taken 8/29/2025 illustrating the tank battery location (blue polygon).

