

Inspection Photos

API: 041-06005

Operator: CHANCELLOR EXPLORATION CO

Inspection Date: 12/16/2025

County: EL PASO



Inspection Photos



Photo 1. Drone aerial photo facing north toward the historic wellsite.



Inspection Photos



Photo 2. Drone aerial photo facing south toward the historic wellsite.



Inspection Photos



Photo 3. Center of the location facing north.



Inspection Photos



Photo 4. Center of the location facing west.



Inspection Photos



Photo 5. Center of the location facing south.



Inspection Photos



Photo 6. Center of the location facing east.



Inspection Photos



Photo 7. North side of the location facing west. There are shallow depressions that remain in this area which are revegetated.

