

WELL NAME: APACHE CANYON 11-10V, API #: 071-07418, INSP. # 716301900



PHOTO 1: WELL SIGN



Network: Dec 18, 2025 at 12:25:56 PM MST
Local: Dec 18, 2025 at 12:25:56 PM MST
+37.096930, -104.964343
Los Animas County

PHOTO 2: LOCATION.



PHOTO 3: UNUSED EQUIPMENT (1" RISER). REMOVE OR MARK RISER PER RULE 606. CA DATE 1-18-2026.



PHOTO 4: AREA OF IMPACTED SOIL NEAR COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,,(2).D. CA DATE 1-18-2026.



PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 1-18-2026.



Network: Dec 18, 2025 at 12:39:57 PM MST
Local: Dec 18, 2025 at 12:39:57 PM MST
+37.096759, -104.964653
Los Animas County

PHOTO 6: OILY WASTE IN COMPRESSOR SKID WITHOUT WILDLIFE PROTECTION SCREENS OR COVERS. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 12-19-2025.