

Inspection Photos

12/16/2025

Operator: LARAMIE ENERGY LLC #10433

Location ID: 334495

Inspection Doc: 718101011

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334495



Photo 1: Photos 1-2 taken from the west end of the WPS. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334495



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334495



Photo 3: Photo shows Label on tank is peeling. Maintenance advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334495



Photo 4: Photo taken from the interim areas on the east end of the Location, facing north. Vegetation appears to be progressing towards 1003 standards, though additional seeding efforts may be necessary.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334495



Photo 5: Photos taken from the interim areas on the west end of the Location, facing south and north respectively. Areas appear to be progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334495



Photo 6: Photo taken from the southwest end of the Location. Photo shows a “disc golf” cage. Location appears to be in use as part of a disc golf course.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334495



Photo 7: Photos taken from the southwest end of the working pad surface, facing west and southeast respectively. Photo shows platforms and a bench on the Location in use as part of a disc golf course.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334495



Photo 8: Photo taken from the southwest end of the Location, facing southeast. Location appears to be in use as part of a disc golf course; photo shows a roped path-way that appears to be used to access the working pad surface of the Location, and platforms.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334495



Photo 9: Photo taken from the northeast end of the Location, facing southwest. Photo shows a “disc golf” cage installed above the tank battery. Location appears to be in use as part of a disc golf course.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources