

Inspection Photos

API: 071-08354

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 12/18/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road. There is erosion along the side of the road and stormwater is not being directed toward the culvert.



Inspection Photos



Photo 2. Facing east along the access road. This culvert is filled in with sediment..



Inspection Photos



Photo 3. Facing northwest toward the wellsite.



Inspection Photos



Photo 4. Facing northwest toward the wellsite.



Inspection Photos



Photo 5. Facing northwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-08354 | Date: 12/18/2025