

Inspection Photos

API: 071-07630

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 12/18/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the access road. There are signs of erosion in this area which is not stabilized.



Inspection Photos



Photo 2. Facing northeast toward the location.



Inspection Photos



Photo 3. Facing north along the west fill slope.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07630 | Date: 12/18/2025

Inspection Photos



Photo 4. Facing toward the pit that remains. The slope of the pit is not vegetation and there are signs of erosion.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07630 | Date: 12/18/2025

Inspection Photos



Photo 5. Facing toward the northeast corner of the location. This area is not stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 6. Facing south at the northwest side of the location. There are signs of erosion along this slope.



Inspection Photos



Photo 7. Facing back northeast toward the slope shown in the previous photo.

