

Interim Reclamation and Stormwater Inspection

December 16, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 336349

Well Name: WOOLEY #13-14

Inspection Document #: 718601246

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WOOLEY #13-14
Location ID: 336349



Photo 1. Looking south down the access road. Access road appears to have been recently graded.




Photo 2. Looking at the pump jack. Undesirable weeds such as kochia are present on the location.



Inspection Photos
Location Name: WOOLEY #13-14
Location ID: 336349



Dec 16, 2025
41° NE
ECMC

Photo 3. Picture taken at the wellhead. Fluid was visible on the upper valve and beneath the valve.



Dec 16, 2025
334° NW
ECMC

Photo 4. Looking north across the location. Weeds are present on location. The location size has been reduced and desirable perennial vegetation appears to be progressing in the interim area.

