

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404474675
Receive Date:
12/18/2025
Report taken by:
Taylor Robinson

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers Phone: <u>(970) 304-5000</u> Mobile: <u>()</u>
Address: <u>1099 18TH STREET SUITE 1500</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Lauren Hoff</u>	Email: <u>RBUEUF27@chevron.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 35522 Initial Form 27 Document #: 403802992

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-29313</u>	County Name: <u>WELD</u>
Facility Name: <u>Village 16S-DU</u>	Latitude: <u>40.401000</u>	Longitude: <u>-104.890080</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SENE</u>	Sec: <u>16</u>	Twp: <u>5N</u>	Range: <u>67W</u> Meridian: <u>6</u> Sensitive Area? <u>No</u>

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Grassland
Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

NA

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- X E&P Waste
Other E&P Waste
Non-E&P Waste
Produced Water
Workover Fluids
Oil
Tank Bottoms
Condensate
Pigging Waste
Drilling Fluids
Rig Wash
Drill Cuttings
Spent Filters
Pit Bottoms
Other (as described by EPA)

DESCRIPTION OF IMPACT

Table with 4 columns: Impacted?, Impacted Media, Extent of Impact, How Determined. Rows include UNDETERMINED GROUNDWATER and SOILS.

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the Village 16S-DU wellhead cut and cap and flowline removal. The wellhead was cut and capped per ECMC rules on 11/19/2024. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

X Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Soil samples were taken at the flowline endpoints, and along the flowline at any points of material change and/or hammer unions, and directional changes.

Proposed Groundwater Sampling

X Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during the site investigation, a grab groundwater sample will be collected and analyzed for all organic and inorganic compounds per ECMC Table 915-1.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the wellhead and flowline areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. A detailed summary of flowline decommissioning activities, including field notes, site photos, figures, and laboratory analytical results, was attached within the approved remediation workplan (Doc. #403880634).

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 5
Number of soil samples exceeding 915-1 2
Was the areal and vertical extent of soil contamination delineated? No
Approximate areal extent (square feet) 200

NA / ND

ND Highest concentration of TPH (mg/kg) _____
-- Highest concentration of SAR 2.14
BTEX > 915-1 No
Vertical Extent > 915-1 (in feet) 4

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 915-1 _____

Highest concentration of Benzene (µg/l) _____
Highest concentration of Toluene (µg/l) _____
Highest concentration of Ethylbenzene (µg/l) _____
Highest concentration of Xylene (µg/l) _____
Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

On 06/24/2024, four background soil samples were collected from one distinct location (BKG01) near the wellhead/flowline at the nearby Village 42-16U Flowline (REM #35278). On 10/03/2023, four additional background samples were collected from two soil boring locations (BKG01 and BKG02) at the nearby Village 31-16DU and 41-16DU locations (REM #31056). All background samples were collected from depths of 3 and 6 feet below ground surface (ft bgs) and were analyzed for inorganics and metals in soil per ECMC Table 915-1. The highest background concentration for pH was observed to be 9.08. The highest background concentrations for arsenic, barium, cadmium and lead with a 1.25x multiplier were calculated to be 7.24 mg/kg, 346 mg/kg, 0.453 mg/kg and 13.63 mg/kg, respectively. All constituents at the site in samples collected are within Table 915-1 maximum background limits except for cadmium (FL01R-S; 0.576 mg/kg) and lead (FL01R-W; 30.9 mg/kg).

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

Based on the analytical results collected during the wellhead and flowline decommissioning activities, a supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the lead (FLR01-W@3') exceedance observed during decommissioning. Remedial delineation samples will be submitted for the full ECMC Table 915-1 analysis. Additional background samples (5+) will be collected to determine if the elevated lead and cadmium concentrations are attributed to native soil conditions at the site and will be submitted for ECMC Table 915-1 inorganic and metal constituents. Background samples will be conducted concurrently with the Village 32-16DU (REM #35266) wellhead and flowline. The proposed sample locations are depicted within a previous Form 27 (Doc # 404359008) which is currently "In-Process" on webforms. Sample results will be reported in a subsequent Form 27.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No impacted material caused by oil and gas operations was identified at this time.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Based on the analytical results collected during the wellhead and flowline decommissioning activities, a supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the lead (FLR01-W@3') exceedance observed during decommissioning. Remedial delineation samples will be submitted for the full ECMC Table 915-1 analysis. Additional background samples (5+) will be collected to determine if the elevated lead and cadmium concentrations are attributed to native soil conditions at the site and will be submitted for ECMC Table 915-1 inorganic and metal constituents. Background samples will be conducted concurrently with the Village 32-16DU (REM #35266) wellhead and flowline. The proposed sample locations are depicted within a previous Form 27 (Doc # 404359008) which is currently "In-Process" on webforms. Sample results will be reported in a subsequent Form 27.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during initial decommissioning activities

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other 1Q 2026 Timeline Update

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator does not have site-specific financial assurance for this project; however, Operator has inactive well, blanket, and surface bonding including Surety IDs 106077122, 106473808, and 106473820, as well as commercial general liability and/or umbrella/excess insurance meeting the requirements of Rule 705.b. Operator does not anticipate making an insurance claim for this project.

- Further soil investigation/delineation is required

Costs included herein are estimates only and may change over time based on numerous factors. Accordingly, Operator makes no guarantees as to the accuracy of such cost estimates, thus providing an estimate for the next year below.

Operator anticipates the remaining cost for this project to be: \$ 15000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

- Compliant with Rule 913.h.(1).
- Compliant with Rule 913.h.(2).
- Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 06/20/2024

Proposed date of completion of Reclamation. 03/31/2026

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 02/05/2024

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 06/20/2024

Proposed site investigation commencement. 03/29/2025

Proposed completion of site investigation. 03/31/2026

REMEDIAL ACTION DATES

Proposed start date of Remediation. 03/31/2026

Proposed date of completion of Remediation. 09/30/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been modified to reflect the completion of decommissioning activities at the former Village 16S-DU wellhead and flowline, as well as the necessity for Supplemental Site Investigation (SSI) activities adjacent to the site. The SSI is tentatively scheduled for completion by the end of 1Q 2026.

OPERATOR COMMENT

This Form 27 is being submitted to provide a 1Q 2026 update for the Village 16S-DU wellhead and flowline (REM #35522). No work has been completed since the previous quarterly update (Doc. # 404359008), currently "In Process" on Web Forms. Active negotiations with landowner are in progress regarding access terms and timing.

Based on the analytical results collected during the wellhead and flowline decommissioning activities, a supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the lead (FLR01-W@3') exceedance observed during decommissioning. Remedial delineation samples will be submitted for the full ECMC Table 915-1 analysis. Additional background samples (5+) will be collected to determine if the elevated lead and cadmium concentrations are attributed to native soil conditions at the site and will be submitted for ECMC Table 915-1 inorganic and metal constituents. Background samples will be conducted concurrently with the Village 32-16DU (REM #35266) wellhead and flowline. The proposed sample locations are depicted within a previous Form 27 (Doc # 404359008) which is currently "In-Process" on webforms.

Pursuant to Rule 913.e., quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the SSI will be submitted on a subsequent Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Scott Williamson

Title: Environmental Consultant

Submit Date: 12/18/2025

Email: NorthernColoradoPM@montrose-env.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: 12/19/2025

Remediation Project Number: 35522

COA Type

Description

COA Type	Description
0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

Att Doc Num	Name
404474675	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

User Group	Comment	Comment Date
Environmental	ECMC has processed this form as an update without technical review; no data was attached thus approval of this form does not imply any agreement with comments on completion of site investigation or alteration of site plan. All ongoing/unaddressed comments/COAs from previous Forms remain applicable. Operator shall not delay execution of remedial or investigative actions while waiting for ECMC approval and may request expedited review if necessary.	12/19/2025

Total: 1 comment(s)