

# Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025




Photo # 0023 Entrance to location

Photo # 0075 Location

# Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0024 Location



Photo # 0035 Location

# Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0036 Separator door label contains incorrect operator name and disconnected emergency contact number

Photo # 0040 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0043 Location



Photo # 0044 Methanol tank label contains incorrect operator name and disconnected emergency contact number

# Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0046 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 0056 Unused flowline lacks lockout tagout (OOSLAT)

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0057 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 0058 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



**Photo # 0066 PRV vent line does not comply with CECMC pressure safety device rules**

**Photo # 0074 Location**

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0086 NE corner of location



Photo # 0087 SE corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0088 SW corner of location



Photo # 0089 NW corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



**Photo # 0032 Unused equipment – Chemical tank with containment on location**



**Photo # 0033 Debris on location**

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0034 Debris on location



Photo # 0069 Debris on location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0070 Debris on location



Photo # 0071 Debris on location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



Photo # 0072 Debris on location



Photo # 0073 Debris on location

# Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025




Photo # 0076 Production tank contains disconnected emergency contact number

Photo # 0078 Production tank contains disconnected emergency contact number

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL #397-3G-G1 PAD

Location ID: 335974

Date: 12/12/2025



**Photo # 0081 Production tank contains disconnected emergency contact number**