

Audit Photos


Location Name: LOCIN OIL CORPORATION, GOVT.-68S104W/2SWSW (OWP)

Location ID: 323895

Date: 12/17/2025



Location Overview – Photo #02093



Location – Photo #02094

Audit Photos

Location Name: LOCIN OIL CORPORATION, GOVT.-68S104W/2SWSW (OWP)

Location ID: 323895

Date: 12/17/2025



Location – Photo #02097



Location – Photo #02106

Audit Photos

Location Name: LOCIN OIL CORPORATION, GOVT.-68S104W/2SWSW (OWP)

Location ID: 323895

Date: 12/17/2025



Unlabeled Chemical Tank (Fluid in Tank) – Photo #02095



Unlabeled Chemical Tank (Fluid in Tank) – Photo #02096

Audit Photos

Location Name: LOCIN OIL CORPORATION, GOVT.-68S104W/2SWSW (OWP)

Location ID: 323895

Date: 12/17/2025



Stained Soil – Photo #02098



Wildlife Entry Hazard – Photo #02103

Audit Photos

Location Name: LOCIN OIL CORPORATION, GOVT.-68S104W/2SWSW (OWP)

Location ID: 323895

Date: 12/17/2025



Wildlife Entry Hazard – Photo #02104



Missing Cover/Wildlife Entry Hazard on Plastic AST – Photo #02100

Audit Photos

Location Name: LOCIN OIL CORPORATION, GOVT.-68S104W/2SWSW (OWP)

Location ID: 323895

Date: 12/17/2025



Open-Ended Line on Steel AST – Photo #02105