

Inspection Photos

12/19/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 323875

Inspection Doc: 719200585

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323875



Photo 1: Photos showing an overview of the location looking north and south, respectively. The Corrective Action to perform additional 1004 reclamation efforts remains outstanding.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323875



Photo 2: Photos showing an overview of the location looking east and west, respectively. The Corrective Action to perform additional 1004 reclamation efforts remains outstanding.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323875




Photo 3: Photo showing Russian knapweed skeletons. It does not appear as though weed control has been performed at the location in 2025.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323875



Photo 4: Photo showing an undesirable plant species, likely prickly Russian thistle or kochia, has infested the PA'd wellhead marker area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources