

Inspection Photos
Location Name: Joseph L. Huett Unit C1
Location ID: 318675



Photo 1 Location overrun with dead vegetation.

Photo 2 Wellhead overrun with dead vegetation.

Inspection Photos
Location Name: Joseph L. Huett Unit C1
Location ID: 318675




Photo 3 Location overrun with dead vegetation Wellsite sign.

Photo 4 Location overrun with dead vegetation.

Inspection Photos
Location Name: Joseph L. Huett Unit C1
Location ID: 318675



Photo 5 Ancillary equipment overrun with dead vegetation.

Photo 6 Location overrun with dead vegetation.