

Final Reclamation and Stormwater Inspection

December 18, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 319827

Well Name: AYLOR #3

Inspection Document #: 718601261

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: AYLOR #3/
Location ID: 319827



Photo 1. Looking down the access road towards the well location. Bare soil on the access road is visible. Vegetation on the access road is primarily undesirable weeds such as kochia and ragweed.



Photo 2. Looking south across the location. Production equipment has been removed.



Inspection Photos
Location Name: AYLOR #3/
Location ID: 319827



Photo 3. Picture taken near the location looking east across the access road. A culvert remains in place under the access road.



Photo 4. Looking south from the well on location. Vegetation on the location is primarily undesirable weedy species such as ragweed and kochia. Desirable vegetation establishment was not observed on the location.



Inspection Photos
Location Name: AYLOR #3/
Location ID: 319827



Photo 5. Looking west from the well location see photo 4 comments.



Photo 6. Looking north from the well location see photo 4 comments.

Inspection Photos
Location Name: AYLOR #3/
Location ID: 319827



Photo 7. Looking east from the well location see photo 4 comments.



Photo 8. Reference vegetation to the west of the well location.