

Final Reclamation and Stormwater Inspection

December 18, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 319865

Well Name: AYLOR #2

Inspection Document #: 718601266

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: AYLOR #2/
Location ID: 319865



Photo 1. Looking south down the two track from the main access road irrigation ditch crossing. Vegetation appears to be reflective of the surrounding area. Nearby construction has disturbed a portion of this section of access road.



Photo 2. Looking north from the location along the northern access road. Vegetation on the access road appears to be reflective of the surrounding reference area.



Inspection Photos
Location Name: AYLOR #2/
Location ID: 319865



Photo 3. Picture taken from access road junction to the west of the well location. This portion of the access road appears to have been used for well access around 2014. This section of the access road appears reflective of the surrounding reference vegetation.



Photo 4. Looking across the well location disturbance from the south edge. Vegetation on location consists primarily of undesirable weeds such as ragweed and kochia. All oil and gas equipment has been removed from the location.



Inspection Photos
Location Name: AYLOR #2/
Location ID: 319865



Photo 5. List B noxious weed scotch thistle is present on the location



Photo 6. Looking north from the well location. Vegetation on location consists primarily of undesirable weeds such as ragweed and kochia. Limited desirable perennial vegetation is present on location but the location is not reflective of the reference area. A portion of the location is within an active construction zone.

Inspection Photos
Location Name: AYLOR #2/
Location ID: 319865



Photo 7. Looking west from the well location. See photo 6 comments.



Photo 8. Looking south from the well location. See photo 6 comments.

Inspection Photos
Location Name: AYLOR #2/
Location ID: 319865



Photo 9. Looking east from the well location. See photo 6 comments.



Photo 10. Reference vegetation to the west of the location.

Inspection Photos
Location Name: AYLOR #2/
Location ID: 319865




Photo 11. Aerial photograph taken 06-02-1972. The main access road appears to be preexisting to oil and gas development (red arrows). A two track (blue arrow) appears to exist after the irrigation ditch crossing, possibly along flood irrigation channels. Approximate location is displayed in green.



Inspection Photos
Location Name: AYLOR #2/
Location ID: 319865



Photo 12. Google earth aerial imagery taken 10/2025. A portion of the disturbance area (green circle) for this location is in an active construction area.

