

Final Reclamation and Stormwater Inspection

December 18, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 462729

Location Name: AYLOR-61S67W/20NWSE

Inspection Document #: 718601263

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: AYLOR-61S67W/20NWSE/
Location ID: 462729



Photo 1. Looking northwest down the tank battery access road from the main access road. Wire gate and posts remain. Vegetation on the access road is primarily undesirable weeds such as kochia and ragweed as well as list C noxious weed downy brome.



Photo 2. The tank battery access road travels north around nearby building. Photo taken looking south down the access road towards the tank battery location. An area that appears to have been disturbed by oil and gas is present to the west of the access road (red circle). A single wire fence borders this area (red arrow). This area contains list C noxious weed downy brome.



Inspection Photos
Location Name: AYLOR-61S67W/20NWSE/
Location ID: 462729



Photo 3. Picture Looking south west across the tank battery location. No production equipment remains on the tank battery.



Photo 4. Looking north from the center of the location. Vegetation on the location is primarily undesirable vegetation such as ragweed kochia and list C noxious weed downy brome. Limited amounts of desirable perennial vegetation are present on and around the edges of the location but does not appear to be progressing towards 80% coverage of the reference area.



Inspection Photos
Location Name: AYLOR-61S67W/20NWSE/
Location ID: 462729



Dec 18, 2025
82° E
ECMC

Photo 5. Looking east from the center of the tank battery. See photo 4 comments.



Dec 18, 2025
183° S
ECMC

Photo 6. Looking south from the center of the tank battery. See photo 4 comments.

Inspection Photos
Location Name: AYLOR-61S67W/20NWSE/
Location ID: 462729



Photo 7. Looking west from the center of the tank battery. See photo 4 comments.



Photo 8. Reference vegetation to the west of the tank battery location.



Inspection Photos
Location Name: AYLOR-61S67W/20NWSE/
Location ID: 462729



Photo 9. Aerial photograph taken 06-02-1972. The main access road appears to be preexisting to oil and gas development (red arrows). Approximate tank battery access road and location are displayed in green.

