

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 12/16/2025



Location Overview – Photo #02026



Location – Photo #02027

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 12/16/2025



Location – Photo #02028



Location/Weeds in Secondary Containment/No Labeling on Tank – Photo #02030

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 12/16/2025



Dec 16, 2025 at 13:04:32
+39.326751,-109.005104
Mack CO 81525
United States



Dec 16, 2025 at 13:02:54
+39.326799,-109.005027
Mack CO 81525
United States

**Weeds in Secondary Containment/No Labeling on Tank –
Photo #02034**

Stored Supplies – Photo #02029

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 12/16/2025



Stored Supplies – Photo #02031



Unmarked Deadman – Photo #02035

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 12/16/2025



Missing Tank Cover/Wildlife Entry Hazard – Photo #02033



No BMPs Installed at Water Drainage/Stream Crossing – Photo #02036

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE

Location ID: 312389

Date: 12/16/2025



Dec 16, 2025 at 13:07:40
+39.328312,-109.003856
Mack CO 81525
United States



Dec 16, 2025 at 13:08:02
+39.328327,-109.003765
Mack CO 81525
United States

**No BMPs Installed at Water Drainage/Stream Crossing –
Photo #02037**

**No BMPs Installed at Water Drainage/Stream Crossing –
Photo #02038**