

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 241-36 Pad

Location #: 324333




Photo # 5466 From entrance to location

Photo # 5467 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 241-36 Pad

Location #: 324333



Photo # 5468 Location

Photo # 5469 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 241-36 Pad

Location #: 324333



Dec 23, 2025 at 11:50:44 AM  
+39.485957,-108.170785  
51° NE  
Garfield County



Dec 23, 2025 at 11:52:12 AM  
+39.485968,-108.170737  
53° NE  
Garfield County

Photo # 5470 Location

Photo # 5471 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 241-36 Pad

Location #: 324333



Photo # 5472 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife



Photo # 5473 Debris

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 241-36 Pad

Location #: 324333



Photo # 5474 Debris