


| Site Information | |
|------------------|---------------------------------|
| Site Name | Lot Holdings 1-3 + Loveland 8-3 |
| Date | 12/19/2025 |
| Sampler | Kendra Corea |
| Weather | 17° sunny |



| Gas Meter Information | |
|-----------------------|----------|
| Make/Model | GEM 5000 |
| S/N | 5072 |

| Calibration Information | |
|----------------------------------------------------------------|-------|
| Gas | Time |
| Pure N ₂ | 10/14 |
| Fresh Air | 10/12 |
| 50 ppm CO, 10 ppm H ₂ S | 10/15 |
| 15% CH ₄ , 15% CO ₂ , Bal N ₂ | 10/17 |

| Bump Test | | | | | | |
|-----------|-----------------|---------------------|---------------------|--------------------|------------------------|----------|
| Time | | CH ₄ (%) | CO ₂ (%) | O ₂ (%) | H ₂ S (ppm) | CO (ppm) |
| 1020 | Calibration Gas | 15.0 | 15.0 | 0.0 | 0 | 0 |
| | Readings | 14.9 | 15.0 | 0.0 | 0 | 0 |

| Field Readings | | | | | | | | | | |
|----------------|------|---------------------|---------------------|--------------------|------------------------|----------|--------------|----------------|-----------|----------|
| Point ID | Time | CH ₄ (%) | CO ₂ (%) | O ₂ (%) | H ₂ S (ppm) | CO (ppm) | Purge Length | Sampled? (Y/N) | Sample ID | Comments |
| SVP01 | 1022 | 0.0 | 0.2 | 20.8 | 0 | 0 | 60 | N | | |
| SVP02 | 1023 | 0.0 | 1.4 | 18.9 | 0 | 0 | 61 | N | | |
| SVP03 | 1025 | 0.0 | 0.3 | 20.7 | 0 | 0 | 60 | N | | |
| SVP04 | 1027 | 0.0 | 0.8 | 19.1 | 0 | 0 | 61 | N | | |
| SVP05 | 1028 | 0.0 | 1.0 | 20.3 | 0 | 0 | 60 | N | | |
| SVP06 | 1030 | 0.0 | 0.2 | 20.7 | 0 | 0 | 61 | N | | |
| SVP07 | 1033 | 0.0 | 0.1 | 20.6 | 0 | 0 | 69 | N | | |
| SVP08 | 1034 | 0.0 | 0.9 | 19.1 | 0 | 0 | 63 | N | | |
| SVP09 | 1036 | 0.0 | 0.6 | 19.6 | 0 | 0 | 70 | N | | |
| SVP10 | 1038 | 0.0 | 2.7 | 18.8 | 0 | 0 | 67 | N | | |

Notes and Observations