

# Inspection Photos

12/19/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 324228

**Inspection Doc:** 719200604

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324228



**Photo 1:** Photos showing an overview of the eastern half of the location looking north and south, respectively. The area appears to be dominated by sweetclover.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324228



**Photo 2:** Photos showing an overview of the eastern half of the location looking east and west, respectively. The area appears to be dominated by sweetclover.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324228



**Photo 3:** Photos showing an overview of the western half of the location looking north and south, respectively. This portion of the location is hayed and appears to be progressing towards 1004 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324228



**Photo 4:** Photos showing an overview of the western half of the location looking east and west, respectively. This portion of the location is hayed and appears to be progressing towards 1004 reclamation requirements.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324228



**Photo 5:** Photos showing an overview of the access road leading to the location. The access road did not pre-exist O&G activities. See COGCC Comments on attached inspection for details regarding variance requirements.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324228



**Photo 6:** Photos showing an example of prickly Russian thistle along the access road. Weed control is required. Due to haying activities, the landowner requests that weeds are treated after July and no earlier.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources